

Possible Problem with Spiderbeam

RIGHT

GOOD

DIRECTORS

Red to Red

Blue to Blue

Balun

Standpipe

REFLECTORS

**VERY IMPORTANT !
Do NOT transpose the feedline!**

WRONG

BAD

DIRECTORS

Here the feedline is transposed!

twisted

Red to Blue

Blue to Red

Balun

Balun

Standpipe

REFLECTORS

This is the most common mistake!